

# 9ffcfc`WcXYg`~]gh

---

Models: ACCMI-22VRDC1A  
ACCMI-28VRDC1A  
ACCMI-36VRDC1A  
ACCMI-45VRDC1A  
ACCMI-50VRDC1A  
ACCMI-56VRDC1A  
(Refrigerant R410A)

Error Code	Content	Error Code	Content	Error Code	Content
L0	Indoor Unit Error	LA	Indoor Units Incompatibility Error	d9	Jumper Cap Error
L1	Indoor Fan Protection	LH	Low Air Quality Warning	dA	Indoor Unit Network Address Error
L2	E-heater Protection	LC	ODU-IDU Incompatibility Error	dH	Wired Controller PCB Error
L3	Water Full Protection	d1	Indoor Unit PCB Error	dC	Capacity DIP Switch Setting Error.
L4	Wired Controller Power Supply Error	d3	Ambient Temperature Sensor Error	dL	Indoor Unit CO2 Sensor Error
L5	Freeze protection	d4	Inlet Pipe Temperature Sensor Error	dE	Capacity DIP Switch Setting Error.
L7	No Master Indoor Unit Error	d6	Outlet Pipe Temperature Sensor Error	db	Special Code: Field Debugging Code
L8	Power Insufficiency Protection	d7	Humidity Sensor Error	C0	Communication Error





---

[WWW.ALPICAIR.COM](http://WWW.ALPICAIR.COM)